

## BIMETAL THERMOMETERS.

TEMP	Deg.C.	-20 to + 40	0 to 100
		-20 to + 60	0 to 120
		-20 to + 120	0 to 160
		-50 to + 50	0 to 200
		-50 to + 100	0 to 300
		0 to 60	0 to 400
		0 to 80	0 to 500
			0 to 600

## GAS FILLED THERMOMETERS.

TEMP	Deg.C.	-100 to + 100*	0 to 120
		-100 to + 200*	0 to 160
		-100 to + 300*	0 to 200
		-20 to + 120	0 to 250
		0 to 60	0 to 300
		0 to 80	0 to 400
		0 to 100	0 to 650*

**Other ranges and dual scale subject to availability.**

**\*Additional calibration costs may apply. Consult Sales Office.**

We manufacture a wide range of instruments to customer's special requirements  
We shall be pleased to discuss and advise on your specifications.

Specifications and dimensions given in this leaflet represent the state of engineering at the time of printing.  
Engineering modifications may take place without prior notice.